

REDACTED VERSION

Ecology and Environment, inc.

International Specialists in the Environment

Job Number KJ6102

Removal Site Assessment

Westbank Asbestos

Manso, Jefferson Parish, Louisiana

TOD# 506-9607-012

PAN# 017301SFXX

Master Log #6

Logbook 13 of 26

7/26/99

E & E Job Number KJ6182

Telephone Code Number Baton Rouge Office 504-251-4698

Site Name Westbank Apartment

City/State Manassas / Virginia

TDD 504-9687-812

PAN 8173815FXX

SSID _____

Start / Finish Date 2/13/97 / 3/12/97

Book 18 of 26
2nd
7/26/99

E & E Emergency Response Center: (716) 684-8940

E & E Corporate Center: (716) 684-8060

MEDTOX Hotline: (501) 370-8263

E & E Safety Director (Home): (716) 655-1260

2/18/97

506-9607-012

0703 START Day, Johnson, Naguin, and Lin, and EOE Story, Rhodes, and Sterling arrived on-site.
IT, USACOE, quality, and Nols on-site.

0702 IT held tailgate safety meeting.

0710 IT meeting over.

0712 EOE Rhodes held site safety meeting - see site safety plans. Weather - sunny, high 70, SW wind, 55% humidity. Scope of Work - mark Acon location, public relations, door-to-door site visits.

0732 START Naguin attended meeting with IT, USACOE, quality, and Nols. Quality working on sites 512, 294/295, 216, the go to 576, 220, and 261. Talked about water lead at [REDACTED] (b) (6), and backfilling at 294/295 after removal is completed this morning. START will look at sampling of down water once a month; IT will write a sampling plan and sample the water. Talked about expanding the command for additional room for more crews. 0745 starting on Monday 2/27/97.

0756 Meeting over - START Naguin and Day loading up air monitoring equipment for air monitoring at site 576 in Gretta. EOE Rhodes and Sterling and START Johnson preparing to mark Acon site for removal; START Day working on database after loading up pumps.

0820 EPA monitor called from Dallas - informed START that Johns-Manville people may show up today and for START to refer questions to EPA; however, START can show them the sites as well as the 2 landfills. START Naguin suggested to call COEQ John Shars to be present during the visit; EPA monitor approved. Other EPA region using 0.1 f/m for clearance level indoor. START and EPA will discuss tomorrow about conducting assessment work to gather more data to assist the removal action.

Fay - Naguin

2/18/97

06 - 9607-012

0842 START Nagrin spoke to COEa shop about the job manhole coming to the site. START will be there if they show up and he will come over.

0902 START Johnson and E&E Rhodes and Starling working on marking Acm sites for removal. START Day continued database.

0930 START Nagrin contacted Env C lab about running water sample for asbestos. Cost 225.00 - TDM 3-5 day turnaround - EPA asbestos in Drinking Water Standard >10 micron only counted.

1005 START Nagrin contacted Alde Hussin of Westvege at 341-5983 about the ditch lined with Acm at (b) (6). We met with EPA at USACOE at 1400 hours, Thursday, February 27, 1997.

1030 met with USACOE - want START to collect wastewater for asbestos on a monthly basis. START will consult with EPA master on this issue.

1038 START Nagrin called EPA master about wastewater sample, he explained START collecting the sample; therefore, START and EPA will award TDO tomorrow. START Nagrin began recording analytical method.

1120 START Nagrin and Day on lunch break

1150 START Nagrin and Day returned to command post from 1141/11 Late Entry - START Johnson and E&E Starling and Rhodes on lunch break at 1140 hour.

1210 E&E Starling and Rhodes and START Johnson departed command post to continue marking Acm sites. START Day continued database. START Nagrin working on public relations and scheduling.

1317 START Johnson and E&E Rhodes and Starling continued marking Acm sites, START Day continued database and START Nagrin working on public relations.

Jay - Nagrin

2/18/97

506-9607-012

1400 hour - Representative from Johns-Manville - Schiller arrived on-site include Diane Dudley, Bruce Ray, Brent Bras, Angela Severt, and Betsy Green.

1418 LDFA John Sharp arrived on-site. START Noguia informed her of how many

1423 START Noguia and LDFA Sharp departed command post for site 576 at [REDACTED] (b) (6) to show Johns-Manville people a court room action. Sharp informed START that they still own the property title from a plant man.

1432 Arrived at site 576 - LDFA Sharp showed them the courtyard and how the homeowner tried to encapsulate with concrete.

1452 Departed site 576 for [REDACTED] (b) (6) in Marano

1501 START Noguia, COE Sharp, and John - Manville representative arrived at [REDACTED] (b) (6) in Marano. Record of Acre - driveway - large chunking Acre in soil being removed. Diane Dudley take photographs of site.

1525 Johns-Manville representative collected a sample of the Acre from the driveway - Quality collected Acre sample for them.

1531 Departed [REDACTED] (b) (6) for [REDACTED] (b) (6) Westway then [REDACTED] (b) (6) at [REDACTED] (b) (6) in Westway.

1537 Arrived at [REDACTED] (b) (6) to show the completed site.

1540 Departed for [REDACTED] (b) (6) site.

1542 Arrived at [REDACTED] (b) (6) site. Observed the friability of the Acre in the driveway.

1553 START Noguia and COE Sharp departed one car at [REDACTED] (b) (6) site for the command post. Schiller (Johns-Manville) representative and their contractor ER (R - Southern) departed site.

1603 START Noguia and COE Sharp arrived at command post. Attempted to call EPA math - left message

Start Noguia

2/18/97

506 - 9607-012

1609 STANT Naguin and COED Sharp recalled EPA motto
and briefed him on the Schubel visit

Summary of Visit:

- STANT Naguin and COED Sharp escorted representatives
of Schubel, their attorney, and contractor ERM
on a site tour. The stop was at site 576
where the courtyard was in Gethsemane, removal was about
to begin, then departed for site 220 at [redacted] (b) (6)
at in Manresa where a removal was being conducted,
then for one in Westway where restoration was
completed, then took them to the site at [redacted] (b) (6)
in Westway Site #122. They were trying to
1612 get the definition of finality from STANT and
COED as well as what air monitoring data collected
thus far. All questions except factual information
was referred to the EPA. Schubel representative
Oisin Dudley collected a sample from site #220.

1623 Completed briefing EPA motto, called COED Coltrane
and COED Sharp briefed him on the visit.

1630 STANT Johnson and E-E Rhodes and Stirling working Acm
sites at STANT Day continued database. STANT Naguin
conducting public relations - returning phone call from
anonymus nadine.

1730 STANT Johnson and E-E Rhodes and Stirling returned
to command post from working Acm sites for removal.

1800 all personnel off-site.

Summary of Events on 2/19/97

- representatives of Schubel and their subcontractors with COED Sharp
 - continued working Acm sites, database, and public relations
 - arranged meeting with Lathe + Cade enforcement, and City of Westway
District Plans
 - continue working Acm sites, database, and public relations
- Down - see PAW tracking sheet *Zrosa. Rog*

2/19/97

506-9607-012

0658 START Nagrin, Johnson, Day, and Lin and E&E Storey, Roedl, and Rhodes, and Starling on-site. IT, quality, Nola, and USA COE on-site.

0703 IT held site safety meeting for IT, quality, USA COE, and Nola. Discussed gas leak.

0710 E&E Rhodes held site safety meeting - see site safety plans. Weather - cloudy, high 75°F, 97% humidity, wind E-SW 10-12/kts. Scope of Work - continue working ACM locations for removal, public relations, door-to-door for site access - air monitoring at site 576 in between access is site assessment at site 261 - (b) (6) - Manco.

0730 START Nagrin attended meeting at IT tools with IT, USA COE, and quality. Quality will be working at 576, 220, and 261. Move to 619, 590/591 and 154/155. They need sketch for 619. Shed at site 154/155 - owner wants quality to move - the site has A cm below shed which is on shed. Vacant garden area at site 261. Dug up gate at site 286 today.

0750 Meeting over. START Johnson and E&E Rhodes and Starling preparing to mark ACM sites for removal. START Day helping set up pump at site 576 with START Lin and E&E Storey and Roedl.

0810 START Nagrin departed site for site 261 to look at ACM in garden.

0815 arrived at site 261 - USA COE Bowers and Hobbs deciding strategy. USA COE Hobbs decided to remove the 3-1" thick concrete walkway between the garden to get to the ACM as well as remove ACM below the garden area.

0830 @pent site 261 for site 154/155 for shed to be moved at (b) (6) in Manco. Vacated shed and removed it site and removal procedure.

0902 @pent site 154/155 for command post.

0912 Arrived at command post, Bullshotht of site 154/155. 2 Troy - Nagrin.

2/19/97

JW6-9607-012

0918 Arrived to IT and USACOE about removal and restoration
restoration at 304/305 at [REDACTED] (b) (6)

1000 START Nagrin working with USACOE at IT on problem
sites with restoration site 267 site 304/305. Arranged
meeting with owner at 304/305 tomorrow at 1330 hour. START
Johnson and E+E Blodis and Stanley continued making Acre sites. START
Day working on database: arranged Jefferson Parish Code Enforcement
Via Orosi and La Leche Via Tingo for 1030 hours meeting
tomorrow.

1105 START Nagrin and USACOE Hobya at Bowes departed for site 267.

1113 START and USACOE arrived at 267. No one home. START
Nagrin contacted resident's mother Mrs. Marge
Winesberry and she ^{IMM 2/19/97} approved replacement
with concrete to the end of the house ad rock from
there back.

1150 START Nagrin and USACOE Hobya and Bowes departed
site for command post

1200 Arrived at command post - late entry - E+E Stanley
departed site for Baton Rouge. START Johnson
and E+E Blodis and Stanley on land back. START Day
and Sri and E+E Rovell on land back.

1248 START Johnson and ^{IMM 2/19/97} E+E Blodis and Stanley departed
command post to continue making Acre sites.

1252 START Day and Sri and E+E Rovell off land back. START
Day continued database. START Sri and E+E Rovell back
on land funded.

1258 START Nagrin departed command post to photodocument
and videotape site 576.

1307 START Nagrin arrived at site 576. Had problem
with camera, charged batteries.

1352 Departed site 576 for command post

1408 Arrived at command post. START Day continued
database.

Day - Nagrin

2/19/97

506-9607-012

- 1410 STANT Johnson and E&E Rhodes and Sterling continued marking Acm sites for removal.
- 1515 First rain began this fall. STANT Day departed command post to help turn down air pumps at site 576. STANT Naguin working on site sketches.
- 1534 EPA John Martin arrived on-site.
- 1555 STANT Naguin and EPA Martin ad USACOE Hobbs ad Power departed command post from site 154/155.
- 1602 Arrived at site 154/155 at (b) (6). STANT, EPA, ad USACOE discussed removal and restoration at the site.
- 1701 Departed site 154/155 for command post
- 1712 STANT Naguin and EPA Martin arrived at command post. STANT Naguin going over site sketches with EPA Martin.
- 1740 STANT Johnson and E&E Rhodes ad Sterling return to command post from marking Acm.
- 1800 STANT Johnson ad Rhodes off-site.
- 1803 STANT Day off-site.
- 1809 STANT Lin ad E&E Sterling and Johnson off-site.
- 1830 STANT Naguin and EPA Martin off-site.
- 1842 Summary of Events on 2/19/97

- continued marking Acm sites, database entry ad public relations
- USACOE ad EPA met to review ad restoration procedure.
- worked on older sites for restoration - pre holding sites.

Future Plans

- continue marking Acm sites for removal, database, ad public relations

Home

see PAN tracking sheet

M. Naguin

2/20/97

506-9607-012

0654 START Naguin arrived at command post.

0659 START ^{Tue 2/21/97} Naguin, Li, ad Day ad E&E
Abols, Roelle, ad Starling on-site. IT, Quality,
Nola, ad Urnco on-site.

0701 IT held safety meeting.

0710 Eric Abols held site safety meeting - see site safety plan
Weather - cloudy, high in the 70s, SE wind, high humidity,
50% chance of rain today. Scope of Work - contained
dustline, and ACM locations for removal, public relations,
possible door to door.

0729 START Naguin and FOA manager attended meeting at IT table.
Quality working on 576, 261, 550/591, 154/155, ad
107. Quality new equipment coming today or tomorrow
to clean up areas next week. Discuss problem about
opening gates - may offer the homeowner money to take
care of the fence themselves. Quality will move shed at site
154/155 to get to ACM and remove the strips out. START
will paint strips and not the whole area.

0743 Site 131 - Westwego location - START will call Dan Nola
need to beef up crew to catch up with Quality. Described
restoration on sites. START informed them best materials
at 100% down ad 1400 hours.

0752 Meeting over. START Johnson ad E&E Abols
departed command post to meet ACM ads for removal.
START Naguin going over site sketches with EPA
manager. START Day began entering air data
into site base.

0915 Continued as 0752 entry

0958 Representative from La Gas and Code Enforcement arrived
on-site for Busted gasline meeting. Representatives included:
Code Enforcement Harold _____ ad Louisiana gas
Vic Taylor, David Allman, & Tommy Naguin.

Jay n Nag

2/20/97

J06-9607-012

1000 Roger Clifford briefed all personnel from IT, Quality, USACOE, EPA, START, Code Enforcement, and Louisiana Gas about busted gas lines during excavation.

Louisiana Gas said through Dottie that they could mark lines. OK for Quality to shut off gas and notify gas company.

1009 Two more representatives from Code Enforcement arrived including; Ellen Bourgeois and Don Griffis.
When ever gas was shut off - the house has to be up to code to turn back on. Alguire is under

1030 Embassy at Dodge City to State is Louisiana Gas.
City of Westwego and City of Thibodaux different code enforcement.

1040 START Noggin left meeting. START Johnson and Eve Rhodes
and Dottie returned to ~~the~~ command post from relay Acre site.

1108 Louisiana Gas and Code Enforcement personnel off site.

1115 START Johnson and Eve Rhodes and Sterling on lunch break.

1138 START Noggin and Day on lunch break.

1215 START Noggin and Day off lunch break. START Johnson
and Eve Rhodes and Sterling working A crevasses for removal.

START Day continued database. START Noggin checking
site status.

1315 START Noggin departed command post to meet with
owner of site 304/305 on [REDACTED] in process along
with EPA Matrix.

1330 Arrived at site 304/305 meet with Joe Bettencourt to discuss
restoration.

1353 Departed site 304/305 for [REDACTED] - Westwego

1357 Arrived at [REDACTED] - Westwego to talk to the City of Westwego
about the ditch. Westwego alderman Jason and Robert
Wiley on site to discuss ditch. Mayor Bellut also present.

1400 Begun discussing ditch with City of Westwego officials,
USACOE, and EPA.

Jeanne Noggin

2/20/97

586-9647-012

1408 USA-COE Hobye and Powers, and IT Clifford arrived at 580 Ave C and began discussing the removal of the ACM lining the ditch.

1435 Continued to discuss pipe and cases. 553-5375 is Westwego work #. STANT Noggin will call to coordinate restoration. EPA will remove ACM, pipe already in ditch, soil/sed or limestone in shell hole. City of Westwego will restore area with sand and spread limestone as EPA delivers.

1509 STANT Noggin and EPA Martin departed 580 Ave C - Westwego for command post.

1515 Arrived at command post. Eve Rhodes departed site for 2-hour Louisiana Regulations course. STANT Johnson and Eve Rhodes and Stirling continued working ACM sites. STANT Day departed to assist STANT Lin in reward funded activities.

1607 STANT Naomi and USA-COE Hobye departed command post for site 216 at [REDACTED] (b) (6) - narrow to investigate conflict about restoration.

1614 Arrived at [REDACTED] (b) (6) - observed surveying and area C restoration. Waited for homeowner.

1650 Homeowner never showed up; STANT Noggin and USA-COE departed site 216 for command post.

1702 Arrived at command post. STANT Noggin began working on site sketches and amending TDOs.

1730 STANT Johnson and Eve Rhodes and Stirling returned to command post from working ACM sites.

1825 STANT Noggin, Johnson, Lin, and Eve Rhodes and Stirling at STANT.

1900 Summary of Event on 2/20/97

- Westwego ditch, deteriorating, nearby ACM sites

Ditches/Plans - work sites, amend TAN, database

Phone - see P&W tracking sheet

JMO - Noggin

2/21/97

506-8607-012

0700 START Nagurni, Day, Lin, and E&E Rhodes, Staley, and Powell on-site. Heavy rain and thunderstorms in area. IT, USACOE, quality, and Nola on-site. EPA Martin on-site.

0717 Eric Rhodes held site safety meeting - see site safety plans. Weather - rain, humidity - 93%, temp - 65°F, SE wind, gusts, 50% chance of rain today. Scope of Work - continue marking ACm sites for removal, door-to-door for site access and field disturbance.

0720 Meeting over - IT held their safety meeting.

0730 START Nagurni and EPA Martin attended meeting at IT trailer Site working on TDDs - 107, 157/155, 530/581, and 261. Rain may delay restoration again.

0746 Discussed wear PPE.

0755 Meeting over ^{8:15 AM 2/21/97} Eric Staley departed command post at 0730 hours to finish up vehicle and find up START Johnson. START Day working on air database. START Nagurni working on amending TDDs with EPA Martin.

0820 START Johnson arrived on-site. START Johnson and E&E Rhodes and Staley preparing to mark ACm sites for removal.

1000 START Nagurni continued cost projections to amend TDDs. START Day continued database entry. START Johnson, and E&E Rhodes and Staley continued mark ACm sites for removal.

1110 DOE John Shug called received complaint from [REDACTED] (b) (6)

(b) (6) at [REDACTED] (b) (6) - manure. START informed

him that we were aware of the situation and that EPA Martin contacted Ken Sarie at COHIT about the problem.

DOE Shug said he will also pay a visit to the site.

1145 all personnel on lunch break.

1245 all personnel off lunch break.

START Nagurni continued TDD amendment. START Day continued database. START Johnson, E&E Rhodes and Staley continued marking ACm sites for removal. Day 2

2/21/97

506-9607-012

1410 START Naguin continued work on TDO amendments and public relations. START Day continued database for soil sample. START Johnson, E&E Phifer and Stirling continued marking Acm sites for removal.

1550 START Naguin completed TDO amendments, and EPA Martin sign them, and forced to Hand Johnson and Martin Butledge.

1610 START Day continued database, START Johnson and E&E Phifer and Stirling continued marking Acm sites for removal.

1735 START Johnson, E&E Phifer and Stirling returned to command post from marking Acm sites for removal.

1745 EPA John Mohr off-site for Dallas.

1800 START Naguin, Day, Johnson, Lin, and E&E Phifer, Stirling, and Poell off-site.

1818 Summary of Events on 2/21/97


- amended TDOs and analytical procurement
- continued marking Acm sites for removal
- going over site sketches with EPA
- continued database entry

Future Plans

- no removal by quality tomorrow
- door-to-door for site access and field data sheets for new sites
- continue marking and database entry
- work on POLREP #7

To Do

- see PAX backlog sheet.


Roy Naguin

2/22/97

506-9607-112

0950 after ^{from 2/22/97} speaking to [REDACTED] (b) (6) about his restoration, see sketch, STANT Nagrin and Johnson departed for site 137 at [REDACTED] - Westways (b) (6)

0959 arrived at site 137 - need to cold zone don't recommend with limestone - not a candidate for concrete.

1007 STANT Nagrin and Johnson departed site 137 for site 054
173 West Dr - Westways

1015 arrived at [REDACTED] at 054 to investigate Acre for removal & restoration. (b) (6)

1025 Site 054 recently sold - need new access agreement. STANT Li and E+E Roell arrived to get access agreement and field site sketch from [REDACTED] (b) (6) - Westways. Plot owners name:

1038 STANT finished site 054 - has new owner. But information on site 975 for rental at [REDACTED] (b) (6) Westways.

1042 STANT Nagrin and Johnson departed site 054 for command post.

1056 arrived at command post. STANT Day continued database and STANT Li and E+E Roell, Staley, and Roell conducting door-to-door. STANT going over site sketches with E+E Roell. STANT Johnson going over marking list.

^{from 2/22/97} 1057 all personnel on lunch break

1240 STANT Nagrin working on PDRREP#7.

1248 All personnel returned from lunch break. STANT Day continued checking data. STANT Li and E+E Roell and E+E Roell and Staley directed command post to conduct door-to-door. STANT Johnson organizing command post and getting site supplies.

1450 STANT Li and Roell returned to command post from door to door for site access and field data sheets of new site. STANT Nagrin completed PDRREP#7. STANT Johnson continued to organize command post and STANT Day continued data base of air and soil samples. Dawn Ray

2/22/97

506-9607-012

0757 START Naguin, Johnson, Day, Lin, ad E&E Rhodes, Stirling, and Roedl on-site.

0805 E&E Rhodes held site safety meeting - see site safety plan. Weather - sunny, wind, temp ~50°F, no rain expected, NE wind, low humidity. Scope of Work - continue marking A cm site for removal, door-to-door for site access, field data sheets, PURREP, database.

0810 Safety meeting over. START Day working on database, START Johnson updating marking list, START Lin ad E&E Roedl on removal funded, E&E Rhodes and Stirling going through files for site access.

0825 IT Pat Miller brought site 576 courtyard in Ghetts, START to re-investigate small driveway for A cm or Vela can put in proper drainage.

0850 START Naguin and Johnson delegated command post to re-investigate site 576 for drainage restoration.

0857 arrived at site 576 - Day investigated

(b) (6)

Resident walked up to START teams and claimed to have A cm in yard. START will investigate KJ -

0905 START Naguin walked to (b) (6) and observed no visible A cm at the surface.

0908 START spoke to (b) (6) at (b) (6) - courtyard informed him he found additional A cm in back driveway ad restoration could not proceed until A cm removed - he understood.

0910 START Lin ad E&E Roedl ad E&E Rhodes at Stirling working door-to-door to investigate new sites.

0918 START Naguin and Johnson delegated site 576 for site 109 for site 109 - in Watertown.

0930 START Naguin ad Johnson arrived at site 109 to investigate site for removal. Dog on Dog

2/22/97

SDG-9607-012

1500 E&E Rhodes and Staley returned to command post.
Begin daily summary report and securing site for
the day.

1530 STANT Lin and Johnson and E&E Rhodes, Staley, and
Roell off-site for apartment. STANT Roger and
Dug off-site for Eaton House after summary of Event
entry.

Summary of Events on 2/22/97

- no removal work by Quality today
- restoration work continued
- continued door-to-door for site access and field date
sheets of potential new sites
- completed draft POLREP #7
- investigated problem sites scheduled for removal or restoration.

Future Plans

- return on Monday 2/24/97 to continue surveying sites
since removal crews will be increased to 5 crews
- continue data base and going over site sheets with EPA

Hours

- see PAN tracking sheet.

Dug *Roger*

2/24/97

S06-9607-012

0701 START Johnson, Rhodes, Starling, Roedel, Lin arrive at CP

0704 Johnson, Roedel, Lin attended Safety meeting Rainy 45°.

0715 START Day arrives on site from Baton Rouge office.

0717 Rhodes starts site safety meeting.

0735 Johnson attends IT and ACE meeting.

590 / 591 finish today 122 new site

154 / 155 Menor 576 Donald new site

107 70% done

4 feet deep are 2.6" aside on concrete.

289 check on Phase II for Pat.

2 ~~over~~ backhoes on Donald's Creek

0757 Meeting over. Johnson briefs START Team.

0821 START Johnson, Rhodes, Starling organize marking team paperwork.

Day does air log books data base entry.

0851 START Johnson, Rhodes, Starling depart CP to mark ten sites

START Day continues computer data entry.

0930 Agreement picked up for site on [REDACTED] (b) (6) Haney.

1007 START Johnson, Rhodes, Starling continue marking sites.

Lin, Roedel sampling team continue sampling Day at CP computer work.

1046 Site marking team continues. Sampling team continues.

G Day continues computer work

1200 START Johnson, Rhodes, Starling depart for lunch

1301 Johnson, Rhodes, Starling return to CP from lunch.

Late entry G Day lunch from 11:30 - 12:30.

G Day @ CP from 12:30 - 13:01

Late entry EPA John Martin arrives at CP 10:00 AM.

1316 EPA J. Martin not on site. Johnson waiting for him.

To go over sketches and update him.

1400 Johnson and Day review Property Data and Database. Paperwork at CP.

Late entry 1315 Rhodes and Starling out to Menor and sketch sites.

Jeff Johnson

2/24/97

506-9607-012

- 1405 Lin and Roedel continue sampling team tasks.
- 1431 START John reviews sketches and restorations w/
EPA Martin.
1500. Lin begins Lin and Roedel return to CP. Paperwork.
- 1532: Day continues work at CP. John call residents
about restoration. Stanley and Rhodes marking
and sketching. Roedell and Lin @ CP.
1601. John meets w/ Randy Rivera about restoration.
He says gray limestone is ok in Backyard.
1620. John and Day return phone calls to residents.
1653. Rho (Lin and Roedel depart CP to sample.
and site oversight)
1655. Rhodes / Stanley continue marking.
- 1704 John Martin in meeting w/ ACT & IT personnel
from 14:20 - 1704
- 1715 Start Lin/Roedell return to CP from sampling.
- 1728 Stanley/Rhodes arrive CP from marking.
- 1729 EPT Martin arrives from meeting.
1735. Rhodes / Stanley paperwork for end of day marking
database.
- (Lin/Roedel paperwork and sketches from sampling).
- 1740 All EPA START off site. end of Day

Dairy Summary 2-24-97

- Rainfall all Day long. * fixed PAN horn tracking
- Site marking continued. Sheet & Weekly Summary
- Quality geared up to 5 crews. of sites to people
- Reviewed 12 sketches w/EPA Martin and gave to IT.
- Called on confined restoration w/ residents and owners.

Future Plans -

- Continue marking all week.
- Finish Database to fine up help w/ Sampling team.

Hours

See PAN Tracking sheet

Kev/John

2/25/97

S06-9607-012

0702 START. Johnson, Day, Rhodes, Stanley, Lin, Roedel, EPA Martin
arrive at CP. Rainy, 45°

0704 Lin, Johnson, Roedel attend safety meeting IT.

0708 Safety meeting over.

0710 START site safety meeting by Rhodes.

122	108	90	90 mob	sites to work on today and return to.
122	108	90	90 mob	
155	590/591			
155	590/591	576	mob	

0729 START Johnson and EPA Martin attend meeting
in IT trailer.

107, 154, 155 suspools

33 holes open for Nola. Nola said it has been
rainy and no concrete can be poured.

122 has fence w/ACM chain wall. offer to remove
fence w/ACM and not replace or leave fence + ACM.

0800 Meeting finished. Johnson briefed START team.
Roedel/Lin out to sample.

0815 Johnson/Rhodes/Stanley out to nail sites.
Day in CP. updating FDS database.

0837 Johnson/Rhodes/Stanley @ [REDACTED] (b) (6)
Hawey. Site # 487/488 to nail and probe ACM.
Continues to rain. some preshading of sites may
be done today.

0915 Marking Team probes site 487/488.

0940 Marking team departs for CP for supplies.

0955 Johnson/Rhodes/Stanley depart CP to nail sites
in Hawey. site # 491. Day continues updating
computer Database. M. Lin/Roedel caught up on work.
Johnson instructed them to take city packet
and continue site access.

1021 Naguin/Looney (START) arrive on site.

1107 Johnson/Rhodes/Stanley to CP. Met Looney/Naguin
Kan John

2/25/97

S06-9607-012

Talked about future plans. Lin/Rosel have site access packet to continue access and COS sketching. DS -

1145 START Nagui, Johnson, Day at E&E Loones, Shreveport, on Staking or line break.

1250 START Nagui, Johnson, Day, and E&E Loones, Shreveport, on Staking off line break.

1309 START Johnson, E&E Shreveport departed command post to continue making Acm site. START Day contact database. START Nagui departed to tell E&E Loones to inform equipment it operated.

1400 START Nagui and E&E Looney returned to command post. Cee Amanda Looney then departed with START Lin and E&E Loone to conduct revised funded activities.

1425 START Nagui and EPA Martin departed command post to see removal going on in Shreveport and Westwego.

1537 START Nagui and EPA Martin to command post. START Day departed command post to assist with sampling.

1635 EPA Myron Krouskos, Bob Sullivan, and their wife arrived on site.

1636 EPA Martin departed command post to take EPA Krouskos on a site tour.

1640 START Nagui departed site for Baton Rouge. END

1740. START Johnson/Rhodes/Stirling arrive at CP.

Lin/Rosel/Looney & Day already at CP.

1800 SJRR team departs CP.

Daily Survey 2/25/97

- Continued site marking
- Site Sampling
- Data base entry.

Future Plans

Purchase Paint for Marking for John

2/25/97

SP6-9607-012

Go over sketches w/ J.S. Martin E.P.A.
Mark sites.

Continue access in spare time.

Hours

See PSW Tracking Sheet.

~~Jackie Johnson~~

2/26/97

S06-9607-012

- 0701 START Johnson, Rhodes, Stanley, Lin, Roedel, Looney,
and Day arrive at CP,
0707 Johnson, Looney, Lin and Roedel attend tool box
Safety meeting.
0710 START Site Safety meeting.
108 60% 591 50% 4 crews / 5 maybe
122 76% 90 prepared [REDACTED]
Met Fred @ 590 people behind house for ACM.
Mark 289 (ATSDR study)
0755 START Looney / Lin / Roedel leave CP surveying team
0830 START Johnson / Rhodes / Stanley met IT Perone
@ site 510 to investigate ACM extending
into neighboring property under fence. Johnson
and Stanley probed area on apt side.
No ACM was discovered. IT Perone and
Quality Donald were present. Site sketch
was updated accordingly.
0925 Marking team arrives at Site 289 on [REDACTED] (b) (6)
Marked back yard according to ATSDR study.
0955 Johnson / Stanley / Rhodes arrived @ CP.
Lin / Roedel / Looney at CP doing sketches and
paperwork. Lin said she sent G. Day out
w/ camera and Video camera to photograph
sites.
1024 Johnson / Rhodes / Stanley depart site for marking.
Johnson Received blank check from Tony with IT
to purchase paint later today. G. Day will
purchase paint.
1130 START Johnson / Rhodes / Stanley back to CP.
Lunch Day takes lunch also.
12:01 Johnson / Rhodes / Stanley / Day finish lunch.
12:05 Day continues computer data base and
return phone calls *for John*

2/26/97

506-9607-012

- 1230 Marking team continues marking sites.
- 13:30 SISPRT Johnson/Rhodes/Starky travel to Gif Instruments to purchase marking paint with check from IT (Tooy).
- 14:41 SISPRT Lin/Roedel/Looney continue site oversight and sampling.
- 14:50 SISPRT Johnson/Rhodes/Starky return to CP to make phone call and gather more sites for marking.
- 15:05 Johnson reviews sketches w/ EPA Martin.
- 1556 Marking team leaves CP to mark sites.
late entry G-Day to Bridge City to pickup accrue
1515 - 1556
- 1630 Marking sites, Sampling, Data entry continues. Day (SISPRT) Returns phone calls.
- 1701 Phone calls raise FDS numbers to 1003.
- 1740 Johnson/Rhodes/Starky return to CP.
Lin/Looney/Roedel always @ CP doing paperwork

1800 SISPRT personnel off site for day

Daily Summary


- Sites marked for accu
- Phone calls made
- Sampling team w/ new member Looney being trained.

Future Plans

- Mark sites
- Continue Sampling and removal oversight.
- Call Tooy about air sampling.

Aous

See Dan tracking sheet.



2-27-97

SOG-9607-012

0701 START Johnson / Rhodes / Starkly / Roedel / Lin / Loongy / Day
and EPA Martin arrive at C.P.

* 261 will go back (Anomaly) and dig up to 18"
in garden area.

Today: 591, 576

removal: 99, 24, 34

* 261 ~~to~~ gasoline was pulled up.

Gas lines yellow. Toy bricks pipe locator for
gasoline locating. 27 wants START to mark
gas lines.

0745 IT meeting ended.

0750 Site access team Rhodes / Starkly out to
obtain access and CD's sketches.

0800 G-Day continues updating Database.

0830 Johnson reviews sketches and makes
phone calls to owners about restoration.
G-Day Continues Data Base.

Lin / Loongy / Roedel Supply Team continues
supplying and takes Site access pocket
for Westwego.

Rhodes / Starkly site access for Hammons.

1031 Few new sites assigned by phone calls.

J. Martin wants to go to site
#122 to talk to resident about
restoration. Johnson called [REDACTED] @
(b) (6)

1035. She will be home to talk to
J Martin also wants to go to #1576

@ [REDACTED], Create to run plan
(b) (6)

for drainage.

1130 START Johnson / Rhodes / Starkly / Day & EPA Martin
to lunch

1230 Johnson & EPA Martin to site #122 about
restoration. Karen John

2-27-97

506-9607-012

1337 Day return to CP. Rhodes/Stanly out to do site access.

1413 Johnson leaves w/ Rhodes/Stanly for Markby and site access and ~~IT~~.

Day continues Database.

1505 Site marking of large site on [REDACTED]

(b) (6) [REDACTED] Day helps supply team.

1600 Activities continue. no new changes.

1701 Supply Team splits up (in/Day and Looney/Roedel

Johnson/Rhodes/Stanly site access for problem sites

1730 Markby team calculates 49 sites ahead of IT and Quality for removal.

1805 Stanly/Rhodes en route back to CP.
Lin/Looney, Day/Roedel Supply team still in field.

1808 Rhodes/Stanly return to CP after receiving access.

1825 Lin/Looney/Roedel come at CP.

1830 Rhodes/Stanly/Johnson off site w/ Day

1847 Roedel/Lin/Looney off site.

Duty Sunny.

- See Daily Sheet

- Site access received.

- PR w/EPA Martin

Future Plans

- Supply

- Markby.

- PR & Review of sketches w/ EDA Martin.

- and Owners of property -

File Hours

See P&W Tracking Sheet.

Ron John

2-28-97

S06-9607-012

- 0656 START Johnson / Stanley arrive on site @ CR
 0700 START Day / Rhodes / Rodel / Looney on site.
 0710 START Site Safety meeting by Rhodes
 all START attended.

0714 Weather 98° Humidity, Hugs 80°, Winds 10-15 mph,
 Dizzle and fog in morning.

- 0731 IT ~~Act~~ meeting started.
 No restoration this weekend. too wet.
 Quality networking either.

591 finish this morning. 34 start

90 99% 99 80%

24 start 513, 261 ready

resample 261 (garden) maybe 331

The Quality will start 5 crews.

0755 IT meeting over.

- 0815 Johnson debriefs START team
 Lin / Looney / Rodel off site to do sampling.
 Johnson / Rhodes / Stanley to mark sites.

6 Day out to site access.

- 0910 Sites visited are #955 on
 (b) (6) [REDACTED], Cedarua Team mystery
 and found No visible fern

- 1000 Sampling team resamples #261
 in rear garden area. Owner wants
 to replace area w/ soil to plant
 turnips.

1110. Site access continues to sites 989
 and 997 both no visible fern
 at either site.

- 1130 Johnson / Rhodes / Stanley / Day to lunch.

- 1230 Johnson / Rhodes / Stanley / Day return to lunch.

- 1315 Day does Database work.

and Site access, phone calls.

Kris John

2-28-97

SO6 - 9607-012

Late entry: 1030 EPA Martin followed
John/Rhodes/Sturdy to site #605.
Produce stand on [REDACTED] (large site)
(b) (6)

Martin said would offer no comment.
He will talk to owner himself.

1430 Sets access controls, Sampling.

1540 START Team gets called to
site #024 on [REDACTED]

Acm is extending around shed.

Area. Acm is probed and marked.

1601 Rhodes obtains new access and FDS
from resident at site #1005.

1710 Rhodes/John/Sturdy return to CP
Day out PR and accessing sites.

1721 Johnson/Sturdy/Rhodes clean van
out. Relieve Tis clean, update
Sketch #24. Copy goes to Pot(1T).

1T (Ted & Roger) told Johnson that the
Tiger Box will be moved soon.

START Needs to move all material
out into Duty's small shed.

START will do it SAT.

Late entry: 1645 Looney takes him to airport.

1800 Sturdy/Rhodes/Johnson/Rhodes/Day
off site. Looney went to
APT.

Late entry Looney returns home from airport c 6:45
Duty Summary

- PR w/ EDA Martin
- Site access / Marking / Sampling
Plans

Saturday activities

Hours: See Pot Tracking sheets. Kof/DR

3-1-97

506-9607-012

0801 START Rhodes / John / Rooney / ¹⁰³Stanley / Day / Roedel
anne @ CD.

0805 Johnson / Day / Roedel / Stanley unloaded Conex
box two white shed of Nola's.

0810 START Rhodes / Rooney out to site access.

0900 Finish unload Conex Box to
Nolas Shed.

0910 Note : Quality, Nola, IT and ACE
Not on site.

1030. Day / Rooney / Rhodes / Stanley off site
to airport and return to Baton Rouge

1040. John and Roedel return rental
car and Station wagon to get Van.

1100 Roedel / John to Enterprise to
rent Van and Return Car & Station wagon.

1213 Roedel / John off site -.

Day, Sunny

= Unload Conex box to Nolas Shed.

- Site access
- No removal or restoration work due to rain.
- Switched vehicles out at Enterprise.

Future Plans

- START Wetherich / Hammitt / Ribera anne @ 12:00
- Mark sites and sketch
- Data Mgr will also arrive.

Hours

- See P&W Tracking Sheet

Kathy Johnson

3-3-97

S06-9607-012

0700 START Johnson/Looney/Roedel arrive @ CD. Roedel/Looney attend Toolbox safety meeting.

0717 #34 is to be visualized first by START team.

0735 IT, ACE, EPA, Nola, Quality meeting in trailer.

24, 79, 570, 571, 34, ? 261 ? 576

4 crews

The One plane + Elec.

108 on hold 15% asbestos mixed.

0801 Meeting ended in trailer.

0805 Johnson briefed START team on sites to be worked @ today

0807 Roedel/ Looney out to sample.

0810 Johnson called by IT to [REDACTED] 570/571
to remark back area and drain.
Paint had been washed away by rain.

0820 Driveway on left of #570 showed
cut edges of ACM. Johnson noted
as found the entire driveway to be
ACM under <4" cover (gravel).
IT will remove driveway. Spoke to
owner she wants limestone.

0850 John return to CD.

0910 Return phone calls. Fax weekly info.

0935 START Watcher arrives on site.

He continues phone calls to apologize
for open restoration holes.

1005 Johnson gets called back out to
[REDACTED] to investigate chunks of
ACM in front of 571 in former
Bed Area.

1030 John returns to CD.

1130 START H. Hammet arrives on site

1200 Lunch (Johnson, Hammet, Watcher, Roedel, Looney)
[REDACTED] Kneel John [REDACTED]

3-3-97

SD6-9607-012

- 1300 Return from lunch
- 1305 SRSRT Scott Thrasher and Pillera on site. Pillera leaves with Sapsly team Roedel/Koony. Johnson instructs Thrasher about Data base and sends Hutchins and Hammitt out to do site access and rent car from budget.
- 1400 Thrasher makes phone calls w/ Johnson
- 1450 Site access / Sapsly and PR continues.
- 1600 Johnson gets called out w/ Thrasher to investigate addition acre on [REDACTED] (b) (6) Three small outcrops have been removed. Resident says it is under the entire driveway. SRSRT needs to reassess TUE moving.
- 1700 SRSRT Johnson speaks to ACE Denby about the site. He says he agrees that we can't search for additional acre that is not visible.
- 1730 Set SRSRT team at CP
- 1740 Johnson briefs them on Apartment Structures.
- 1800 Set SRSRT team off site for Day

Daily Summary

- Site access
- Sapsly
- Site reassessment

Future Plans

- Reorganise tiger Box.
- Sapsly, Site assessment.

Hours

See P&W Tracy Street Keep John

3-4-97

S06-9607-012

- 0701 SISR7 John / Hammitt on site.
 0705 SISR7 Day arrives on site.
 0719 Rillera / Wtchurch arrive on site - late due to traffic.
 0721 Ruedel / Looney / Thorsell arrive on site late due to traffic.

0735 Meeting IT trailer:

330/331 Reasses.

108 results cause lack of proceed (b) (6) house)

570/571, 79, 87, 45/46, Joquin 123 after lunch.

WED all parking in State BLDG.

IT Ted directs Quality to keep material wet.

0800 Johnson + Hammitt continue (b) (6)

To probe for additional areas.

Some was found at Surface $\frac{1}{2}$ -1" cover.Quality will bring equipment out
to chase material.0830 Wtchurch phone calls, Thorsell data
base w/ Bay Day.Hammitt and Wtchurch unloaded Tiger
Box from Nola's white Shed.0930 Start Day off site to go to
EPA Methyl Parathion site.

0940 SISR7 Johnson / Hammitt arrive @ CP.

1000 IT Pat wants Johnson to go w/in
to site.

1005 Ruedel / Looney / Rillera supply continues.

1100 SISR7 Wtchurch / Hammitt locate
Acres in cordon and paint area.
near back fence in route.11:10 Johnson left w/ IT Pat to clean up
restoration details at site on

(b) (6)

~~Kad Johnson~~

3-4-97

506-9607-012

1157 Johnson briefed SEC (Dunphy) on Bent
corporation situation and Site # 570/511.
resident unhappy about restoration.

The wants concrete.

(b) (6) Site on [REDACTED] is extending beyond
paved boundaries.

1214 Johnson / Mitchell out to lunch

1255 John in hisa bush. #205 meets
guests (as above).

1315 Johnson / IT Duncan to site 45
ACR extending.

1400 (b) (6) #5745 extends under
sufficient cover in back. Johnson contacted
IT Duncan.

1448 John return to CP. Ruedel / Killen / Looy
Supply continues. Hammett

1546 John continues to deal w/ resident
and owns phone calls.

1706 ^{Hammett} Ruedel / Mitchell site access.

Johnson site oversight and problem solving
Ruedel / Looy / Killen Supply Team
Thorsell database entry.

1733 Ruedel / Looy / Killen / Hammett / Mitchell
drive @ CP to do paperwork.

1800 START off site:

Daily Survey

- Public Relations w/ owners.
- Site access / oversight
- Site supply

Entire Plans

- Site access etc. Same as Survey

Hans

See Pam Tracy sheet

Karl John

3-5-97

506-9607-012

0700 87007 John / Looney / Rodel / Rillera / Thorsell
and Hammitt / Wutchurch arrive at CP.

0703 Rodel / Looney / Rillera attend tool box
Safety meeting.

0705 E&E Site Safety meeting by Rodel.

(b) (6) [REDACTED] to be investigated. Removed
and onto this property.

Unit 337 Maple 5/0/5/11 Call tell
resident ACE Doug White will come by to
visit

0730 Site Safety in one ACE trailer.

87 100%	79 100%	331 100%	45/46 30%
210/211 5%	123 6%	479 324 puped	

Today → 123, 210/211, 8324 481 570/571 45/46
325 next Donald

0815 Wutchurch / Hammitt to Gulf Instruments
for Paint (yellow) for gas lines.

0838. John To [REDACTED] to speak to
come - KJ.

0910 START Nagin arrive on site from Baton Rouge

0937 John To Laroussi #123 to investigate
SEM Paint lines. KJ

1031 Laroussi returns from Laroussi #123.

1101 New trailers for ACE and IT arrive
on site.

1131 Supply Team Rodel / Looney / Rillera arrive
back at CP.

1200 87007 John / Nagin / Wutchurch / Hammitt
and Thorsell out to lunch

1230 Return from lunch (above personnel)

1235 87007 Wutchurch / Hammitt out to do
site access.

15:05 Tracy Bryant on site *Handwritten*

3-5-97

SOG-9607012

1601 SNSR Johnson briefed GRS Bryant
on site information.

Late entry: SNSR Nagin off site
@ approx. 1300.

1700 Supply continues. Roedel / Loring / Rollins
Site access by Witchuck / Hammitt
Thorsell Data Mgmt & phone calls.

17:20 SNSR Johnson & EPA Bryant arrive
at site 45' to respond to call about
kids in front yard on front porch.
Bryant said to air monitor tomorrow.
Donald with Quality set up orange
barrier fence to prevent area around
removal from being entered.

1740 Roedel / Rollins / Loring arrive on site
from supply.

Late entry: Johnson helped 27
Roger and ~~EPA~~ EPA w/ fence and
electric poles around compound. 1300-1500.

1800 SNSR & GRS Bryant off site.

Daily Survey


- SNSR Nagin on site for day also EPA Bryant
- Site access
- New trailers on site for ACE & IT.
- Supply and removal oversight.

Future Plans

- Marking of test + site sketch.
- Supply & air monitoring on Celestine
Dr.

Hours

See DSN Tracking sheet



3-6-97

506-9607-012

0700 S1S2R7 Johnson / Thorsell / Wutchurch / Hammitt /
Ridella / Roedell / Looney

0710 E&E site safety meeting

0713 Hammitt / Wutchurch load air supply
supplies in blue bomb GPA vehicle

0730 Site meeting starts

(45/46) 20% (210/211) 30% (123) 90%

520 30%, 324 100%, (396)

325, 390, 391 definite (starts)

0740 GDA present areas in meeting.

Mark site #43.

0753 Looney / Hammitt Ridella out to sample
and do visual.

0830 Hammitt / Thorsell out to do site access

0900 Wutchurch checks on getting printer
fixed.

0905 Johnson / Roedel set up air pumps to
monitor ambient air at site #045

1000 John returns to CP

1130 Johnson / Hammitt / Wutchurch out to
lunch w/ Thorsell

1200 Return from lunch

1300 Hammitt / Wutchurch out to do
site access.

Thorsell answers phone calls.
as data entry.

Johnson responds to calls from
IT / ACE

Roedell / Looney / Ridella continue
air supply

1410 Johnson to [REDACTED] to get
approval to remove extended area. [REDACTED] John

(b) (6)

3-6-97

506-9607-012

- 1530 Activities continue as before
 1610 John to CP to make public relations phone calls and restoration details and verification
 1705 Ruedel / Pilliar / Looney continue sampling. For daily activities see Sampling Logbook.
 West church / Hammitt continue site access.
 1732 Ruedel / Pilliar / Looney arrive @ CP to do daily paperwork.
 1740 West church / Hammitt arrive @ CP and unload septic tank into Tank Box.
 1800 START personnel off site for Day.

Daily Summary

- Site access
- Sampling
- Public relations w/ restoration

Future Plans
(Same)Hours

- See Rain Tracking Sheet

~~Kathy Johnson~~

3-7-97

S06 - 9607-012

0700 S7SRT Johnson / Looney / Roodell / Billera / Thorsell / Witzelchuk / Hammitt on site.

0701 Johnson / Roodell / Billera / Looney attend tailgate meeting.

0709 S7SRT Safety meeting.
325 remove garden.

0740 Meeting: 45 100%, 46 100%, 396 100%

123 100%, 570 80%, 210/211 95%

start 325, 402, 390 goto, 391 30%, start 576,

210/211 @ 9:00, 619?, 576 end site 2 hrs

3 crews Sat.

Nola: 108/607 200, 573, 511, 512

0810 Meeting over in trailer

Johnson briefs S7SRT team

0830 Billera / Roodell / Looney out to sample and visual removal activities.

0900 Johnson / Witzelchuk / Hammitt out to mark ACM locations and sketch sites.

Thorsell in CP Data Mgmt. and phone calls.

1000 Marking continues.

Sampling continues.

1130 Johnson / Witzelchuk / Hammitt arrive @ CP to go to lunch w/ Thorsell.

1200 Return from lunch.

Johnson gets called out to Celeste Dr. to confirm ACM.

1300 Johnson / Witzelchuk / Hammitt out to continue marking ACM and site sketch.

Sampling continues after their 30 min break.

Karen John

3-7-97

S06-9607-012

1405 On site. @ location on
 (b) (6) [REDACTED] Trailer Park

is full of ACM all over.

Site is sketchy but impossible
 to mark. Johnson informs IT
 Roger Clifford of situation w/ Power
 lines and site marking.

1500 Sampling team continues visual
 and Sampling.

Marking team KJ/RW/MH return
 to CP to gather additional
 supplies and make phone calls.

Thorell informs Johnson of phone
 calls incoming and problems.

1620 Thorell / Wtchuk / Hammitt leave
 to mark one more site for day.
 Johnson remains in CP w/ CPA
 Bryant to speak to home
 owners over phone.

1700 Sampling continues.

Public Relations continues
 Sketching / Marking continues.

1732 Roedel / Luong / Bullen return to
 CP from Sampling for paperwork.

1742 Hammitt / Thorell / Wtchuk return
 from marking and unload van into
 tiger box.

1800 All START personnel leave for day

Daily Summary

Future Plans

- Site marking
- Public relations
- Sampling

- Move into New
 trailer @ CP

Hours: See Pan Tracy Sheet
 Lou Johnson

3-8-97

SD6-9607-012

0655 SWAR John / Thorsell / Hammitt / Looney / Roedel /
Witchuck / Rillera. arrive on site

0700 Rillera / Looney / Roedel attend toolbox safety
meeting.

0730 402 602 after lunch Looney 391 802

20/211 1002 325 tools 390 prepped

570 1002 576 1002 issued 619 prepped.

Today: 390 start moving, 131, 391 move to 402
+ 619 daycare

0801 Meeting ended.

0815 S7SPR Johnson, Witchuck, Thorsell, Hammitt
start moving out of trailer into new
Trailer

0816 Looney / Roedel / Rillera out to Sample.
Three removal crews working.

1045 Looney / Roedel / Rillera return to CP.

1100 Moving is finished into new trailer.

1130 See S1SPR Merle's out to lunch

1230 All S7SPR return from lunch.

1250 Hammitt work on key transfer for
Trailers

1300 Witchuck / Thorsell out to do site
access.

Hammitt / John at CP working on
phone calls and organizing CP

1400 Sampling continues, phone calls
and organization.

1500 Hammitt / John / EPA Bryant call
and Public Relations w/ Home owners.

1515 EPA - Bryant speaks to [REDACTED]
on 537 [REDACTED] (b) (6)

1530 EPA Bryant leave site for
Airport. *Koch John*

3-8-97

506-9697-812

1550 Hammitt continues phone calls
and organizes High Box w/
New CP supplies.

Thorsell/Witcheck return
from site access to CP.

1600 Johnson informs IT David to install
edging @ [REDACTED] + [REDACTED]

1630 Activities continue site access,
phone calls, Sampling

1700 Johnson leaves w/ Witcheck to
go to airport.

1730/1800 STSPT personnel leave site for Day
Daily Summary

- relocate in new trailer
- Site access
- Sampling
- Phone calls / Public relations

Future Plans

- Site access
- Marketing
- Public relations
- CP organization

Hires

See DSW tracking sheet.



3/10/97

504-9607-012

0710 START Frog Naguin arrived on site from Baton Rouge in rented van. START also Rollins and EOE representative Scott Thorsell, Mike Hammitt, Ryan Whitburn, and Amanda Rooney on-site.

0720 START Naguin held site safety meeting - see site safety plans. Weather - fog, 66°F, 40% chance of rain, wind calm. Scope of Work - door-to-door to collect sketch-signatures from owners, continue data base and site files.

0740 START Naguin met with USA-COE Bowers and White and received a list of sites scheduled for removal.

0842 EPA monitor called - will be in late today - 2:00p. EOE Hammitt and Thorsell pulling sketches to get signatures from owners. EOE Whitburn helping COE Rooney and Rollins on removal funded.

1000 START Naguin and EOE Hammitt departed command post for ^{TM 3/10/97} Office Depot to office cabinet and office supplies.

1038 START Naguin and COE Hammitt returned to command post. COE Hammitt and Thorsell began arranging site file.

1139 START Naguin, COE Hammitt and Thorsell on land break.

1230 off land break.

1243 START Naguin, USA-COE Bowers and Montegut departed command post for site 109 - (b) (6) Westwego.

1258 START and USA-COE arrived at site 109 and meet with owner Randy Rivers. He still wants concrete in the yard area, will have to consult with the EPA.

1313 Continued discussion with (b) (6). He is willing to compromise with a 8x10 foot area in front of garage and limestone everywhere else in back yard. He never documents the site as we walked through.

1334 START and USA-COE departed site 109 for command post,

1353 START Naguin and USA-COE Bowers and Montegut returned to command post.
Frog. Naguin

3/10/97

S06-9607-012

1354 E+E Hammitt and Howell working on getting signatures from homeowners on site sketches. STANT Noggin working on site files and logbook for POCREP.

1500 E+E Hammitt and Howell departed command post to get ^{3/10/97} signature from homeowners on site sketches and to investigate new sites.

1512 EPA OSC John Martin arrived on-site.

1609 STANT Noggin, EPA Martin, and USA COE Powers departed command post for site 108 to talk to owner [REDACTED] (b) (6)

1622 EPA and STANT arrived at site 108 T [REDACTED] (b) (6)
in Westways and spoke with [REDACTED] (b) (6). She escorted EPA and STANT around the areas of removal. She explained about her interaction with the USA COE as well as the phone calls.

1645 STANT Noggin and EPA Martin finished talking to Mrs. [REDACTED] (b) (6) and walked over to site 109.

1650 EPA Martin explained putting the concrete in the boat if he an limestone in the front.

1655 STANT Noggin and EPA Martin departed for command post

1705 STANT Noggin and EPA Martin arrived at command post.

1730 E+E Hammitt and Howell returned to command post.

1800 STANT and E+E personnel departed site for apartment

1912 Summary of Events on 3/10/97

- continued public relations - especially at sites 108 and 109

- EPA spoke to resident at site 109 about problem

- continued getting signatures from homeowners on site sketches

- bought new file cabinet and refilled paperwork.

- continued investigation of new possible sites

Future Plans

- continue public relations and door-to-door.

Notes

- see PW tracking sheet

Noggin

3/11/97

506-9607-012

0635 START Noggin, EOE Looney, Dillera, Whitchurch, Thorne, and Hammitt on-site. EPA Martin on-site. IT, Nola, USACOE, and Quality on-site.

0700 IT and Barnes held tool box safety meeting - discussed best stess, traffic on streets.

0705 IT, tool box safety meeting over.

0708 EOE Whitchurch held site safety meeting - see site safety plan. Weather - temp ~69°F, 97% humidity, variable wind, 20% chance of rain.

0723 START Noggin attended meeting at IT trailer. Nola - site 308, 309, ad 310 80% complete, site 511 funded, 513 needs ad, son, the sites Nola will be working on. Site 103, 519, 520 will go over with USACOE motto get for restoration. Quality working on 415, 408/409, 379, 571, 014, ad 390 sites today. Discussed repairing damaged stes around areas of removal.

0810 Meeting over. EOE Hammitt and Whitchurch working on getting signatures on site sketches for restoration. START Noggin showing EOE Looney and Dillera how to calibrate a low flow pump.

0830 EOE Hammitt and Thorne departed command post to get signatures on sketches. EOE Whitchurch going through file to get sketches for signatures.

0902 START Noggin departed command post for sites 570 ad 571 - Shetler.

0910 START Noggin arrived at sites 570 ad 571 to update sketches

0937 START completed investigation of sites 570 ad 571 ad departed for [REDACTED] (b) (6)
- March.

0943 Arrived at site [REDACTED] (b) (6) - Monroe - observed ACM under steps - IT
^{Temp-14°}
~~Dilger~~ Dilger - she - will encapsulate ACM under stairs.

0946 START Noggin departed for site 379 at [REDACTED] (b) (6) to observe ACM under walkout concrete. USACOE Barnes will assist.

1002 arrived at site 379 at [REDACTED] (b) (6)

1018 USACOE Barnes arrived - he will address the walkout concrete with ACM

1040 START Noggin departed for site 103 ad 108 in [REDACTED] (b) (6) - Westway
- rough - Noggin

3/11/97

506-9607-012

1056 START Pagan arrived at sites 108 to show Nola ad USA Co E restoration at site 109 to get homeowner signature for restoration

1101 (b) (6) at site 109 signed sketch for restoration

1107 START Pagan went over site 108 with Nola Monroe ad USA Co E montgomery board (b) (6) request for restoration.

1120 START Pagan departed site 108 for command post

1135 START Pagan arrived at command post. COED Sharp on site talking to EPA Martin.

1200 all START and EDE personnel on lunch break.

1200 all personnel off lunch break. EDE Hammett working on site file for sketches. EDE Jarsell ad Whitham preparing for door-to-door for site sketches - to get signatures.

1335 EDE Whitham and Jarsell departed command post for door to door, site supplies, ad photo ad video documentation.

START Pagan working on schedule.

1445 EDE Hammett continued calling resident ad EDE Whitham and Jarsell continued door-to-door for site access and signature for ^{TMN 3/11/97} site sketches for restoration. START Pagan working on site sketches.

1600 Continued as 1445 hours entry.

1743 EDE Jarsell ad Whitham returned to command post

1804 EDE Jarsell, Hammett, Whitham, Sooney, Billera

off-site. START Pagan discussing project with EPA Martin.

1838 START Pagan off-site. EPA Martin remained on site.

1902 Summary of Events on 3/11/97

-continued door-to-door for site access and signatures on sketches

Future Plans

-continued to investigate new sites and get signatures on sketches

Items

-see PAN tracking sheets

Frank Pagan

3/12/97

506-9607-012

0650 START Nagurni and Ede Hammitt on-site. IT, Nola, USAID, and Quality on-site. A light rain is falling.

0654 EPA Martin on-site.

0700 Quality held tool box safety meeting - went over PPE.

0706 Ede Whitham held site safety meetings - see site safety plans. Weather - cloudy, light rain, variable wind, temp ~65°F, high ~75-77°F. Scope of Work - continue door-to-door for signature on sketch, new sites, site files, public restoration and help in decision making.

0728 START Nagurni and EPA Martin attended meeting in USAID trailer. Quality working on 415, 408, 366, 570, 014, 390, 408¹⁰¹, 365 starting, and 571. will also start 109.

Return to 379 on Amex and START will update sketch. Later

^{from 3/11/97} open one to 46 sites. Site has gumbel cars. JSMC

0739 and EPA will talk to owner at site 571 about restoration.

Nola working on six sites to pour concrete.

0749 Meeting over. School bus - site 079

0754 Ede Hammitt and Whitham departed command post to conduct door-to-door and video and photo documentation. Ede Whitham working on site files and cell phones.

0909 START Nagurni and EPA Martin departed command post for site 571 about restoration.

0918 START Nagurni and EPA Martin arrived at site 571 to speak to Mr.

and Mrs. (b) (6) about restoration

0938 (b) (6) signed std sketch. START & EPA will look at plan and talk to new resident

0942 START and EPA looked at gas line/resident sleeping.

0945 START and EPA departed site 571 for (b) (6) to attempt to meet with (b) (6)

1012 START Nagurni contacted (b) (6) arrives at 366-5035 who will come out and meet with EPA Martin to settle restoration.

1046 (b) (6) arrived at (b) (6) and began to talk to EPA Martin.

1038 Note: hold off on removal at (b) (6) - damage site # 514

dmn Nag

3/12/87

506-9601-012

1050 after (b) (6) discussed the replacement of material for thinning, in which he wanted concrete, did not like limestone, then he departed.

1103 START Naguin and EPA Martin returned to command post -

STANT Naguin notified USA COE and IT Roger Clifford not to conduct removal tests site 514 until further notice.

1150 START Naguin and E&E Whithurd, Thorsell, and Hammitt on lunch break.

1220 START Naguin off lunch break - working on site sketches to investigate

1250 E&E Personnel off lunch break. Preparing for door-to-door.

1320 E&E Hammitt and Whithurd departed command post to get signature on site sketches for restoration.

1345 START Naguin departed command post to investigate site 079 at (b) (6)

(b) (6) in Westwego for restoration. E&E Thorsell continued calling residents at site for filing.

1400 Arrived at site 079 - entire remittance was Acm - need to replace with limestone - tell to own door restoration.

1409 Arrived at site 108 for signature on sketch. START Naguin spoke to

(b) (6), went over restoration, he agreed; however, want myself to sign off.

1427 START Naguin departed for (b) (6) in Bridge City to investigate Acm in remittance.

1438 START Naguin arrived at (b) (6) in Bridge City to investigate road of Acm on property.

1442 Area in question at (b) (6) in Bridge City was not Acm but concrete. START Naguin departed for command post.

1458 Enroute to command post START Naguin stopped at (b) (6) site #408/409 to analyze restoration.

1517 START had homeowner sign site sketch for restoration at site 408/409. He also agreed with L shaped concrete at site 600 - his home.

1530 START Naguin returned to command post. E&E Whithurd and Hammitt continued door-to-door for signatures on site sketches and investigated new sites. *Zrog - Nag*

3/12/97

506-9607-012

1545 START Nagurni going over site sketches with EPA Martin.

1620 E+E Whitelund and Hammitt returned to command post to get more sites for signatures. E+E Jorsell continued calling homeowners

^{FM 2/12/97}
1635 E+E Whitelund and Hammitt departed command post to continue getting signatures from homeowners.

1655 E+E Jorsell continue calling residents and S+T Nagurni continued going over site sketches.

1720 E+E Hammitt and Whitelund returned to command post. STARS and E+E began finding work for the day.

1755 STARS Nagurni and E+E representative Hammitt, Sooney, Rillera, Jorsell, and Whitelund off-site. EPA Martin remained on-site.

1812 Summary of Events on 3/12/97

- continued door-to-door for investigation of new sites
- site file, signature for restoration on sketches

Future Plans

- continue door to door, possibly mark ACW sites for removal.

Hours

- see PSW tracking sheet


1/105
Page

48

3/12/97

SD6-9607-012





ecology and environment, inc.

Recycled Paper/569129